

***126 (T) (12/22) INDIA – WEST COAST – Port Dabhol – Buoys.**

Source: Konkan LNG LTD.

1. Channel buoys are temporary removed from KLL navigational channel Port Dabhol in the following coordinates:-

Bouy No.	Light Type	Position
Fairway	Fl(2)10s	17° 34'·34N., 73° 04'·58E.
1	Q.G	17° 33'·49N., 73° 05'·65E.
2	Q.R	17° 33'·64N., 73° 05'·74E.
3	Fl.G.10s	17° 32'·96N., 73° 06'·44E.
4	Fl.R.10s	17° 33'·13N., 73° 06'·49E.
5	Fl(2).G.15s	17° 32'·43N., 73° 07'·18E.
6	Fl(2).R.15s	17° 32'·54N., 73° 07'·30E.
7	Fl(3).G.10s	17° 32'·02N., 73° 07'·71E.
8	Fl(3).R.10s	17° 32'·11N., 73° 07'·90E.
9	VQ	17° 31'·03N., 73° 08'·68E.
10	Q(9)	17° 31'·13N., 73° 08'·84E.
GL 11	Fl.G.10s	17° 31'·42N., 73° 08'·22E.
GL 12	Fl(2)G.15s	17° 31'·23N., 73° 08'·41E.

2. Mariners are advised to navigate with caution in the area and contact Port authority for latest information.

Charts affected – 21 – 22 (INT 752) – 293 (INT 7022) – 256 (INT 7340) – 212 –2065