

<b>*093 (T) (13/24)</b>	<b>INDIA – EAST COAST – Kamarajar Port – Buoys.</b>
Source: Kamarajar Port Limited.	
1. Following Temporary buoys are deployed at various positions for Rehabilitation and Retrofitting of the damaged portions in North break Water (NBW) for safe navigation:-	
Sl No.	Position
(i)	13° 15′·60N., 080° 21′·06E.
(ii)	13° 15′·50N., 080° 21′·08E.
(iii)	13° 15′·45N., 080° 21′·08E.
(iv)	13° 15′·38N., 080° 21′·09E.
(v)	13° 15′·31N., 080° 21′·11E.
(vi)	13° 15′·24N., 080° 21′·09E.
(vii)	13° 15′·19N., 080° 21′·15E.
(viii)	13° 15′·24N., 080° 21′·21E.
(ix)	13° 15′·30N., 080° 21′·24E.
(x)	13° 15′·39N., 080° 21′·22E.
(xi)	13° 15′·50N., 080° 21′·20E.
(xii)	13° 15′·61N., 080° 21′·17E.
<b>Charts Affected – 32 (INT 754) – 33 (INT 755) – 391 –356 (INT7400) – 313 – 3001 (INT 7402) – 3028 (INT 7404).</b>	