

INDIAN NOTICES TO MARINERS



EDITION NO. 05 DATED 01 MAR 2023

(CONTAINS NOTICES 054 TO 062)

REACH US 24 x 7



msis-inho@navy.gov.in
inoh@navy.gov.in



+91-135-2748373



National Hydrographic Office
107-A, Rajpur Road
Dehradun – 248001
INDIA



Commander (H)
Maritime Safety Information Services
+91- 135 - 2746290-117

WWW


www.hydrobharat.gov.in

CONTENTS

<u>Section No.</u>	<u>Title</u>
I	List of Charts Affected
II	Permanent Notices
III	Temporary and Preliminary Notices
IV	Marine Information
V	NAVAREA VIII Warnings in force
VI	Corrections to Sailing Directions
VII	Corrections to List of Lights
VIII	Corrections to List of Radio Signals
IX	Corrections to Miscellaneous Nautical Publications
X	Reporting of Navigational Dangers

(PUBLISHED ON NHO WEBSITE ON 1ST & 16TH OF EVERY MONTH)

FEEDBACK: msis-inho@navy.gov.in



INSIST ON INDIAN CHARTS AND
PUBLICATIONS
Original, Authentic and Up-to-Date



© Govt. of India Copyright

No permission is required to make copies of these Notices. However, such copies are not to be commercially sold.

II

MARINER'S OBLIGATION AND A CHART MAKER'S PLEA

Observing changes at sea proactively and reporting them promptly to the concerned charting agency, is an obligation that all mariners owe to the entire maritime community towards SOLAS. Mariners are requested to notify the Chief Hydrographer to the Government of India at the above mentioned address/fax number/ E mail address immediately on discovering new or suspected dangers to navigation, changes/ defects pertaining to navigational aids, and shortcomings in Indian charts/ publications. The Hydrographic Note [Form IH – 102] is a convenient form to notify such changes. Specimen form is attached at Section IX with this notice. Also visit our website for downloading and filling up instructions for Hydrographic Note.

**Chief Hydrographer
to the Government of India**

WARNING AGAINST USE OF COUNTERFEIT PRODUCTS

All mariners are cautioned against the use of counterfeit copies of IN Charts and publications. Navigational Charts produced after 31 Oct 14 carry NHO crest as watermark on the reverse with backslip. Chart Agent's stamp is mandatory on all Charts.

Counterfeit products may have errors resulting in potential risks. The same are not approved by inspecting agencies and do not satisfy the carriage requirements of SOLAS chapter V.

Mariners are strongly advised not to use or encourage the use of counterfeit charts and publications. Failure to comply with the warning may invite legal action.

III

EXPLANATORY NOTES

Corrections to Charts and Publications. Section I comprises List of Charts affected by the notices contained in this edition. Whereas sections II and III contain information for correcting the charts and publications. Mariners should insist on corrected charts from their chart distributors/agents.

- (a) Geographical positions given are in the horizontal datum of the current edition of the chart, unless otherwise stated.
- (b) Bearings are true, reckoned clockwise from 000° to 359°. Bearings to lights are from seaward.
- (c) Symbols referred to, are those shown on the chart 5020 (INT 1).
- (d) Alterations to depth contours, deletion of depths to make way for new detail, etc; are not normally mentioned, unless they have some navigational significance.
- (e) Blocks and notes, if any, accompanying the Notices in Sections II and III are placed after Section IX.

Temporary and Preliminary Notices. These are indicated by (T) and (P) respectively after the Notice number and are placed in Section III. SI Nos. of those in force are published quarterly on 01 Jan, 01 Apr, 01 Jul and 01 Oct, and their text is published in Annual Edition of Indian Notices to Mariners. They should be inserted in pencil, by the user, on receipt.

Source of Information. A star preceding the number of a Notice indicates that the notice is promulgated by INHO based on original information received.

Sailing Directions. Corrections for the Sailing Directions (Pilots) are given in Section VI.

Lights. Corrections to Indian List of Lights are given in Section VII, where affected Light List number is quoted.

- (a) These corrections should be incorporated as per instructions given on page XI of the List of Lights.
- (b) Such correction notices to list of lights may be published in either an earlier or a later Edition of N to M than the Edition containing the Notice to the chart correction.
- (c) The range of a light given is its nominal range. Its geographical range is given in parenthesis only if it is less than the nominal range.
- (d) A star indicates that the corresponding field is to be amended and all stars indicate that new light is to be inserted.

Radio Signals. The corrections in Section VIII should be cut and pasted in the appropriate volume of the List of Radio Signals.

Radio Navigational Warnings.

- (a) These are broadcast as serially numbered NAVAREA warnings by the concerned NAVAREA coordinator through GMDSS and Area Radio Broadcasts.
- (b) They contain important information affecting navigational safety, which cannot await the publication of the next edition of N to M.
- (c) It should be borne in mind that they may be based on reports which cannot always be verified before promulgation.
- (d) It is therefore necessary to be selective, and promulgate only the more important warnings to avoid over loading users; the less important information is included in the forthcoming edition of N to M or the Chart/Publication concerned.

IV

Laws and Regulations. While in the interest of the safety of shipping, the Hydrographic Office makes every endeavor to include in its publications details of the laws and regulations of all countries pertaining to navigation, it must be clearly understood: -

- (a) That no liability whatsoever can be accepted for failure to publish details of any particular law or regulation and
- (b) That publication of details of a law or regulation is solely for the safety and convenience of shipping and implies no recognition of the International validity of the law or regulation.

Correction of Charts and Publications by the Users. Notices to Mariners contain important information concerning safety of navigation at sea, hence, they should be used to keep the specified charts and publications up-to-date.

Reliance on Charts and Associated Publications. While every effort is made by the Hydrographic Office to ensure the accuracy of the information on Charts and Publications before they are published, it should be appreciated that it may not always be complete and up-to-date. The mariner must be the final judge for the reliance he can place on the information available, bearing in mind his particular circumstances, local pilotage guidance and judicious use of available navigational aids.

Use of Global Positioning System (WGS 84) positions.

- (a) The positions of hydrographic objects shown on some of the Indian charts and publications are in Everest datum. However, the positions of vessels obtained from Global Positioning System (GPS) are on World Geodetic System 1984 datum. There will always exist difference in the position values obtained by visual fixing (Everest Datum) and GPS position (WGS 84 datum).
- (b) Wherever these differences have been ascertained, their average values are published as a Cautionary Note on the chart concerned, as shifts in Latitude and Longitude. Whilst plotting GPS positions on charts, the shift values as given on the chart must be applied, before making any assessment of the navigational situation vis-à-vis the other charted information.
- (c) These datum shift values are not uniform, particularly in areas off Andaman and Nicobar and Lakshadweep Islands, as these places are not linked to mainland network (Everest datum). Mariners are advised to use alternate source of position information such as Visual or Radar, particularly when closing the shore or navigating in the vicinity of dangers.

Source Data on Charts. All Indian charts contain specific information on their source of hydrographic data. In areas where the source data is very old, incomplete and less reliable, the mariner must use such charts with prudence. Mariner should always use the largest scale charts available for the area. Apart from being the most detailed, the larger scale charts are usually corrected first. Hydrographic information may be sparse on small scale charts. On such charts, a charted shoal may be in error as regards position, least depth and extent. Uncharted dangers may also exist, particularly in areas away from well-established routes. Mariners must exercise due caution.

Further Guidance. The Mariner's Hand Book (NP 100) gives full explanation on the use of charts and the type of information contained on charts. In their own interest, all users of charts should refer to it.

NEWLY PUBLISHED INDIAN CHARTS, ENC_s AND PUBLICATION

1. The new Indian Charts that are available for mariners in the market are as follows:-

<i>Chart No.</i>	<i>Date of Publication</i>	<i>Title, Limits & Description</i>	<i>Scale</i>	<i>Folio</i>	<i>Price</i>
NIL					

2. The new edition Indian Charts that are available for mariners in the market are as follows:-

<i>Chart No.</i>	<i>Date of Publication</i>	<i>Title, Limits & Description</i>	<i>Scale</i>	<i>Folio</i>	<i>Price</i>
NIL					

3. The Indian Charts that are permanently withdrawn are as follows:-

<i>Chart No.</i>	<i>Date of Publication</i>	<i>Title</i>	<i>On Publication of New Chart/ Edition</i>	<i>Date of Publication</i>
NIL				

4. The new Indian Electronic Navigational Chart that are available for mariners in the market are as follows:-

<i>ENC Cell Name</i>	<i>Chart No.</i>	<i>Title</i>	<i>Issue Date</i>
NIL			

5. The new edition Indian Electronic Navigational Chart that are available for mariners in the market are as follows:-

<i>ENC Cell Name</i>	<i>Chart No.</i>	<i>Title</i>	<i>Issue Date</i>
NIL			

6. The Indian Electronic Navigational Charts that are permanently withdrawn are as follows:-

<i>ENC Cell Name</i>	<i>Chart No.</i>	<i>Title</i>	<i>Issue Date</i>
NIL			

7. The forthcoming Indian Charts is as follows:-


<i>Chart No</i>	<i>Title</i>	<i>Scale</i>	<i>Remarks</i>
2025	RELIANCE TANKER BERTHS	7500	New Chart

VI

Availability of ENC's

The complete folios of Official Indian ENC's are distributed worldwide through JEPPESEN MARINE (formerly C-MAP), UKHO and Norwegian Hydrographic Service. UKHO distributes Indian ENC's through the worldwide network of their agents and distributors. Updates are also made available as per the existing policy of the distributor. Mariners and other ENC users may contact the under mentioned for further details:


United Kingdom Hydrographic Office Admiralty Way, Taunton, Somerset TA1 2DN, UK Tel : +44 (0) 1823 337900 Fax : +44 (0) 1823 330561, 1823 284077 Web site : www.hydro.gov.uk	M/s IIC Technologies Limited B-2-350/5/B-22, Road No. 3 Banjara Hills, Hyderabad - 500 034 Telangana Tel: +91 4039144444 Fax: +91 4039144455 Email: somnath.marthi@iictechnologies.com Web: www.iictechnologies.com
M/s Primar Norwegian Hydrographic Service, Postbox 60, 4001 Stavanger Norway Telephone - +47 - 51 85 87 00 Fax - + 47 - 51 85 87 08 E-mail: data@ecc.no Website: - www.primar.org	



SECTION – I

The list of charts affected by the Notices 054 to 062 contained in this edition is as follows:-

CHART NUMBER	FOLIO NO.	NOTICE NO.
21	2	056 (T), 057 (T)
22 (INT 752)	3	056 (T), 057 (T)
31 (INT 756)	5	055, 058 (T), 061 (T)
32 (INT 754)	5	058 (T)
41 (INT 757)	6	060 (T)
207	2	054, 056 (T)
209	3	056 (T)
210	3	056 (T)
211	3	056 (T), 057 (T)
253 (INT 7328)	2	056 (T)
254 (INT 7331)	3	054, 056 (T)
255 (INT 7334)	3	056 (T), 057 (T)
256 (INT 7340)	3	056 (T)
292 (INT 7021)	2	056 (T), 057 (T)
293 (INT 7022)	3	056 (T)
354 (INT 7408)	5	058 (T)
355 (INT 7405)	5	058 (T)
391	5	058 (T)
2101 (INT 7347)	3	056 (T)
2512 (INT 77396)	1	062 (P)
3010 (INT 7418)	5	059 (T)
3041	5	059 (T)



SECTION – II**PERMANENT NOTICES*****054 (05/23) INDIA – WEST COAST – Diu Head to Gopnath Point - Buoy**

Source: DLL, Jamnagar.

Chart 254 (INT 7331) [previous update NE 15 OCT 2022]

Move		Fl(9)15s No 7	From	20° 57′.70N., 72° 07′.84E.
			To	20° 56′.00N., 72° 09′.40E.

Chart 207 [previous update NE 15 SEP 2022]

Move		Fl(9)15s No 7	From	20° 57′.70N., 72° 07′.84E.
			To	20° 56′.00N., 72° 09′.40E.

***055 (05/23) INDIAN – OCEAN – Bay of Bengal – Northern Portion (Krishnapatnam to Bassein River) – Wrecks**

Source: BNHOC Notice No. 03/2023.

Chart 31 (INT 756) [previous update 04/23]

Insert		21° 42′.14N., 90° 58′.81E.
Delete		21° 41′.12N., 90° 58′.46E.
		21° 39′.07N., 90° 54′.32E.
		20° 59′.28N., 91° 55′.51E.

Section – III**TEMPORARY AND PRELIMINARY NOTICES**

1. It is brought to the information to the users that same or all information contained in this Temporary Notices to mariner may have been included in the relevant ENC's.
2. New TPNMs are now part of ENC updates from 01 Oct 22 onwards.
3. All in force Temporary and Preliminary Notices are available for visualisation along with details of affected Charts and ENCs for mariners on **INDIAN WARNINGS INFORMATION AND NAVIGATION SERVICES (INDIA – WINS)** on www.hydrobharat.gov.in.

*056 (T) (05/23)	INDIA – WEST COAST – Arabian Sea – Oil Rigs.
Source: NCD, Mumbai.	
1. List of Oil Rigs is as follows: -	
Rig Name	Position
Aban III	18° 40'.37N., 72° 21'.47E.
Aban IV	19° 34'.72N., 71° 20'.64E.
CE Thornton	19° 26'.11N., 71° 24'.16E.
Aban VIII	18° 44'.50N., 72° 19'.63E.
Compact Driller	21° 01'.91N., 72° 33'.25E.
Discovery 1	19° 15'.95N., 72° 06'.05E.
DS Fossil	19° 21'.43N., 71° 17'.06E.
DS Fortune	18° 34'.48N., 72° 16'.76E.
FG MC Clintok	20° 41'.85N., 71° 44'.81E.
Foresight Driller IX	18° 18'.63N., 72° 21'.81E.
Great Drill Chauru	19° 36'.62N., 71° 20'.66E.
Great Drill Chetna	18° 47'.74N., 71° 15'.67E.
Great Drill Chaaya	18° 38'.79N., 72° 14'.94E.
Great Drill Chitra	18° 56'.92N., 72° 15'.93E.
Jindal Star	18° 33'.72N., 72° 17'.66E.
Jindal Supreme	18° 46'.85N., 72° 17'.12E.
JT Angel	20° 11'.52N., 71° 52'.25E.
Jindal Explorer	19° 13'.35N., 72° 10'.87E.
Parameswara	19° 31'.76N., 71° 17'.39E.
Ron Tappmeyer	20° 37'.32N., 71° 38'.77E.
Sagar Vijay	20° 24'.79N., 69° 22'.51E.
Sagar Jyoti	19° 10'.62N., 70° 53'.02E.
Sagar Kiran	20° 25'.80N., 71° 54'.61E.
Sagar Ratna	19° 14'.67N., 71° 19'.47E.
Sagar Shakti	20° 20'.87N., 72° 13'.94E.
Sagar Uday	19° 23'.15N., 71° 51'.37E.
Sagar Gaurav	19° 39'.07N., 71° 55'.36E.
Trident 2	19° 33'.38N., 71° 19'.70E.
Trident 12	19° 07'.39N., 72° 06'.44E.
Vivekananda 1	19° 08'.72N., 71° 55'.25E.
Vivekananda 2	18° 39'.22N., 70° 58'.86E.
Virtue 1	19° 10'.61N., 70° 57'.65E.
Victory Driller	19° 15'.66N., 71° 21'.21E.
2. All Highlighted Oil Rigs reflects changes in position of respective Oil Rigs from previous Notice.	
3. All vessels operating in vicinity are to maintain a clearance of 01 NM off the oil rigs.	

4. All positions referred to WGS 84 datum
Charts Affected – 21 – 22 (INT 752) - 292 (INT 7021) – 293 (INT 7022) – 253 (INT 7328) – 254 (INT 7331) – 255 (INT 7334) – 256 (INT 7340) – 207 – 209 – 210 – 211 – 2101 (INT 7347)
Former INTM 050 (T)/23 is cancelled.

***057 (T) (05/23) INDIA – WEST COAST – Satpati to Dighi Harbour – Salvage operation.**

Source: Directorate General of Shipping, Mumbai

1. Salvage operation of Barge “PAPAA 305” is being carried out by vessels, ‘TAKLIFT 7’ in the following coordinates:-

Sl No.	Position
(a)	19° 15′.87N., 72° 20′.64E.
(b)	19° 14′.86N., 72° 20′.64E.
(c)	19° 14′.86N., 72° 21′.70E.
(d)	19° 15′.87N., 72° 21′.70E.

2. During the operation period, anchoring, fishing and trawling are prohibited within 4 Km and the vessels are advised to keep proper clearance of 1 NM × 1 NM from above mentioned area.

3. Mariners are advised to navigate with caution in the area.

Charts affected – 21 – 211 – 22 (INT 752) – 255 (INT 7334) – 292 (INT 7021)

*058 (T) (05/23)	INDIA – EAST COAST – Bay of Bengal – Oil Rigs.
Source: NCD, Mumbai.	
1. List of Oil Rigs is as follows: -	
Rig Name	Position
Aban II	16° 20′.51N., 81° 55′.45E.
DDKG 1	16° 32′.23N., 82° 35′.69E.
Platinum Explorer	16° 24′.97N., 82° 22′.69E.
Olinda Star	16° 23′.09N., 82° 21′.60E.
Key Singapore	16° 27′.76N., 82° 10′.64E.
West Polaris	16° 16′.06N., 82° 23′.17E.
2. All Highlighted Oil Rigs reflects changes in position of respective Oil Rigs from previous Notice.	
3. All vessels operating in vicinity are to maintain a clearance of 01 NM off the oil rigs.	
4. All positions referred to WGS 84 datum.	
Charts Affected – 31 (INT 756) – 32 (INT 754) – 391 – 354 (INT 7408) – 355 (INT 7405).	
Former INTM 048 (T)/23 is cancelled.	

*059 (T) (05/23)	INDIA – EAST COAST – Paradip Anchorage – Buoys.		
Source: Paradip Port Trust.			
1. Following Navigational buoys are withdrawn temporarily for repair and maintenance:-			
Sl No.	Nomenclature	Position	Characteristics
01.	Green Buoy (Stbd) No 1	20° 12′.82N., 86° 46′.32E.	Fl.G.3s
02.	Red Buoy (Port) No 2	20° 12′.58N., 86° 46′.17E.	Fl.R.3s
Charts affected – 3010 (INT 7418) – 3041			

***060 (T) (05/23) BAY OF BENGAL AND ANDAMAN SEA – Andaman Sea – Installation Activities.**

Source: Myanmar Notice 03/2023.

1. Undersea Telecommunication Cable Laying is being carried out in following areas till 15 April 2023.

(a) The repair of the defective cable is being carried out by the ROV (Remotely Operated Underwater Vehicle) along the following coordinates.	
Sl No.	Position
01.	15° 25′.98N., 96° 31′.96E.
02.	15° 12′.82N., 96° 29′.08E.
(b) The new cable laying and connecting is being carried out by the ROV along the following coordinates.	
Sl No.	Position
01.	14° 46′.42N., 96° 23′.52E.
02.	14° 44′.85N., 96° 23′.43E.
(c) New cable laying cross PTTEP gas pipeline is being carried out by the ROV along the following coordinates.	
Sl No.	Position
01.	14° 12′.38N., 96° 21′.34E.
02.	14° 11′.84N., 96° 21′.34E.
(d) The installation of the main sub-line unit (1) is being carried out by the ROV along the following coordinates.	
Sl No.	Position
01.	14° 07′.38N., 96° 22′.42E.
02.	14° 06′.63N., 96° 22′.11E.
(e) The installation of the main branch unit (1) is being carried out by the ROV along the following coordinates.	
Sl No.	Position
01.	14° 07′.67N., 96° 23′.06E.
02.	14° 07′.16N., 96° 22′.41E.
2. Mariners are advised not to navigate, anchor or trawl within 500 km along the submarine cable laying and repairing coordinates and consult the local port authorities for the latest information.	
Charts affected – 41 (INT 757)	

***061 (T) (05/23) INDIAN – OCEAN – Bay of Bengal – Northern Portion (Krishnapatnam to Bassein River) – Installation Activity**

Source: Myanmar Notice 04/2023.

1. Offshore Jacket Installation Survey is being carried out by Installation vessel, “**HYUNDI 2500 (Call sign; 3FRA3)**” Support vessels “**Lanpan 26 (Call Sign;S6LP6)**” and “**Lanpan 34 (Call Sign;9V2757)**” in the following coordinates till 30 Apr 2023.


Sl No.	Position
(a)	19° 41′.80N., 92° 30′.80E.
(b)	19° 41′.81N., 92° 34′.24E.
(c)	19° 38′.56N., 92° 34′.25E.
(d)	19° 38′.55N., 92° 30′.81E.

2. During the operation period, anchoring, fishing and trawling are prohibited within 4 Km and the vessels are advised to keep proper clearance from above mentioned area.

3. Mariners are advised to navigate with caution in the area.

Charts affected – 31 (INT 756)

*062 (P) (05/23)	INDIAN OCEAN – MAURITIUS – Agalega Islands – Jetty Construction.
Source: IH – 102 INS Darshak.	
1. New Jetty Construction is being carried out in the area bounded by the following coordinates :-	
Sl No.	Position
(a)	10° 20′.54S., 56° 35′.05E.
(b)	10° 20′.68S., 56° 35′.06E.
(c)	10° 20′.68S., 56° 35′.07E.
(d)	10° 20′.69S., 56° 35′.18E.
(e)	10° 20′.68S., 56° 35′.18E.
(f)	10° 20′.68S., 56° 35′.07E.
(g)	10° 20′.54S., 56° 35′.06E.
2. Mariners are advised to navigate with caution in the area.	
Charts affected – 2512 (INT 77396)	



SECTION – IV

MARINE INFORMATION

1. **NAVTEX TRANSMISSION**

Status of MSI Promulgation by NAVTEX Stations is as follows:-

Mauritius (Cassis)	- Operational
Seychelles (Mahe)	- Operational
Myanmar (Yangon, Myeik, Kyau Phyu)	- Operational

Following new NAVTEX stations along the Indian coast have commenced operations:-

INTERNATIONAL NATIONAL NAVTEX FREQUENCY - 518 kHz								
Sl.	Station Name	B1	Broad Cast Timings in UTC					
			0110	0510	0910	1310	1710	2110
(a)	Veraval	H	0110	0510	0910	1310	1710	2110
(b)	Vengurla Point	J	0130	0530	0930	1330	1730	2130
(c)	Muttam Point	L	0150	0550	0950	1350	1750	2150
(d)	Porto Novo	O	0220	0620	1020	1420	1820	2220
(e)	Vakalpudi	Q	0240	0640	1040	1440	1840	2240
(f)	Balasore	S	0300	0700	1100	1500	1900	2300
(g)	Keating Point	V	0330	0730	1130	1530	1930	2330

2. **MISIDENTIFYING FISHING BOATS AS PIRATE SKIFFS**

All merchant vessels entering Indian EEZ are advised that dense fishing activity may be encountered off West Coast of India. Fishing is generally carried out by mechanized boats and single hull boats with outboard motors carrying 4-5 crews using long lines upto 50 NM from coast. The vessels traversing the nets are likely to be approached by fishing boats for safeguarding nets and lines and should not be mistaken as skiffs and PAG's. Masters of vessels to report any suspicious activity of fishing vessels immediately to MRCC (Mumbai) on telephone +91-22-24388065, 24316558, Email: - mrcc-west@indiancoastguard.nic.in. Any suspicious activity of skiffs/ boats to be photographed if possible. Merchant vessels with armed guards on board are to report presence of guards to Indian Navy/Coast Guard while transiting Indian EEZ.

3. **DISPLAY ANOMALIES IN ECDIS**

(a) Mariners are advised that the International Hydrographic Organization (IHO) check data set shows that some ECDIS systems fail to display some significant underwater features in the standard display mode. The use of this check data set, issued through ENC service providers and available from the IHO website www.iho.int, to check the operation of ECDIS is strongly recommended. JRC has confirmed that certain versions of JRC ECDIS fail to display some types of wreck and obstructions, including stranded wrecks, in any display mode. Where JRC ECDIS is in use, paper charts should be the primary means of navigation until the ECDIS has been proved to operate correctly. See www.jrc.co.jp/eng/product/marine/whatsnew/20120313/index.html for further information.

(b) Some Electronic Chart Display and Information Systems (ECDIS) may exhibit operating anomalies. The International Maritime Organization's (IMO) circular SN.1/CIRC.312 pages /imodocs.aspx (registration required) lists identified anomalies, Their characteristics and remedial advice. Mariners are reminded that they should access the International Hydrographic Organization (IHO) data presentation and performance check (DPPC) dataset (news links of <http://www.iho.int/srv1>) and ensure that all installed ECDIS units are checked.

4. **SAFETY FAIRWAYS, RECOMMENDED ROUTES, TRAFFIC SEPARATION SCHEME**

The Director General Shipping has established Safety fairways, recommended routes and traffic separation scheme (TSS) in restricted Indian waters including the offshore development area to enhance safety of navigation. The details of coordinates are published in the fortnightly Indian Notices to Mariners.

(a) **Safety Fairways:** An area within which permits are not granted for the erection of oil or gas related structures. The use of a safety fairway is not usually mandatory, but is recommended. Safety fairways have been promulgated in and round offshore development area in Arabian Sea up to the Exclusive Economic Zone (EEZ) due to increased weather related marine accidents and dense traffic. These are mandatory for all Indian ships and vessels transiting through the ODA and recommendatory for all foreign flag ships and vessels irrespective of size.

(b) **Traffic Separation Schemes (TSS):** The TSS is mandatory for all Indian and foreign flag ships and vessels entering and leaving.

5. **GAGAN SYSTEM COMMISSIONED FOR OPERATIONS**

The GAGAN System is now commissioned for safety of life, civil aviation, and en- route operations in addition to all other non-aviation applications. The GAGAN signal is being broadcasted through GSAT-8 and GSAT-10 with PRN127 & 128 respectively. All the GPS users are requested to enable SBAS functionality in their receivers, configure it to receive PRN- 127 & 128 and avail the benefits of GAGAN in terms of increased accuracy and reliability. There may be occasional signal outages due to system up-gradation activities.

6. **USAGE OF THURAYA/ IRIDIUM AND SATELLITE PHONE**

(a) The use of Thuraya, Iridium and other such satellite phone is banned in India under Sec 6 of Indian Wireless Act and Sec 20 of Indian Telegraph Act. It is intimated to all shipping companies/ shipping agents that use of Thuraya/ Iridium and other such satellite phones are banned in Indian waters and seafarers should not use the same.

(b) Satellite phones can be used only after no objections certificate issued by department of telecommunication (DOT) on a case to case basis. The shipping agents should mandatorily intimate the details of person carrying Thuraya and the particulars of Thuraya, Iridium and other such sets in Pre Arrival Notification on Security (PANS).

(c) The unauthorized holders of Thuraya/ Iridium and other such Satellite phones can be prosecuted under Sec 6 of Indian Wireless Act and Sec 20 of Indian Telegraph Act.

7. **CAUTIONARY NOTE**

There is a finite amount of lag between publication of large and small scale Indian Nautical Charts. To avoid uncertainty the mariners are advised to use large scale charts for coastal navigation wherever applicable and available. In addition, mariners are to refer large scale charts in conjunction with small scale charts in areas where both overlap during both planning and conduct of passage.

8. **ADVISORY FOR ALL VESSELS NAVIGATING INDIAN WATERS**

(a) All vessels navigating in Indian waters are cautioned to keep a sharp look-out for fishing vessels and small crafts, as there have been several incidents of collisions with such vessels in the past resulting in loss of innocent lives as well as damage to property.

(b) It is further cautioned that all vessels need to exercise extreme care while navigating during hours of darkness as such vessels are generally of primitive built (wood/fibre/etc) due to which it may not be detected on ship's radar, especially during adverse weather conditions. Also, such vessels may not be properly lit, or sometimes, only one vessel may be lit among multiple vessels in a cluster.

(c) The general areas of concern on the west coast of India are the areas of convergence and divergence of traffic, mainly between Mangalore to Kanyakumari (Cape Comorin). Further, in these areas, additional caution needs to be exercised and wide berth be given to all such vessels.

(d) All fishing vessels are also cautioned to avoid fishing in areas having high density traffic. All fishing vessels are also required to always maintain proper lookout by sight, hearing and by all available means and comply with all applicable provisions of Collision Regulations.

List of Indian Chart Agents

<p>OSA Books and Periodicals R-246, Greater Kailash –I, New Delhi - 110 048 Tel/Fax: +91-11-26418643, 46557337, Mob: 9971093992 Email: rpani246@gmail.com</p>	<p>M/s VDO Marine Instruments Shanghar Building, PO Bag No – 645, 45/271, Corner of Bristow & Naval Road, Willingdon Island, Kochi – 682 003 Tel: +91 484 2667157 Fax: +91 484 2667121 Email: atmain@md4.vsnl.net.in</p>
<p>M/s Global Charts & Nav. Aids Pvt. Limited 1A, Goa Mansion, Ground Floor, 58, Dr. SunderlalBahl Path (Goa Street), Fort, Mumbai - 400 001 Tel: 91-22-22626318, 22626380 Fax: 91-22-22621488 Email: sales@globalcharts.in Web: www.globalcharts.com.sg</p>	<p>SMS Marine Private Ltd 505, Raheja Arcade, Sector 11, CBD Belapur, Navi Mumbai – 400 614 Tel: +91-22-62233326, Fax: 022-67939504 Mobile: +91 9820 238 542 Email: info@c-map.co.in , raj.chakravorty@smsmap.com Web: www.smsmaps.co.in</p>
<p>M/s C & C Marine Combine 25 Bank Street, 1st Floor, Fort Mumbai - 400 023 Tel: 91-22- 22660017/0018/0525/1937 Ext: 32 Tel: 91-22-22672143 Fax: 91-22-22670896 Email: vijay@ccmarine.in, sales@ccmarine.in</p>	<p>M/s Global Marine Infratech Pvt. Ltd. SikshaSandan, Ground Floor, Plot No. ND7, VIP Area, IRC Village, Bhubaneswar – 751015 Tel: +91-674-2550599, Fax: +91-674-2551899 Cell: - +91-9337477799, 7077702499 Email: tusarkantha@gmiindia.in Web: www.gmiindia.in</p>
<p>M/s JM Maritime Services 24/24C Kavarana Building, Ground Floor, WadiBunder, P.D. Mellow Road, Mumbai – 400 009 Tel: +91 22 23736956, Fax: 022 - 23725083 Cell: +91 9820788357 Email : jmms@mtnl.net.in , charts@mtnl.net.in</p>	<p>L. R. Marine Services 301, 3rd Floor, Biryra House, 265, PerinNariman Street, Fort, Mumbai - 400 001. Tel: +91-22-2269 1535, Fax: +91-22-66359148 Cell No: +91 8108926880/ +91 98214 60258 Email: lrcharts@gmail.com, lrmarine@live.com</p>
<p>M/s Lift o Marine Allen's Mansion, C6, Nungi Station Road, Bata Nagar, Kolkata – 700 140 Tel: +91 9836972027 Fax: 033 24924283 Email: sankar@liftmarine.org, liftmarine77@gmail.com Web: www.liftmarine.org</p>	<p>IIC Technologies Limited 8-2-350/5/B-22, Road No. 3, Banjara Hills, Hyderabad – 500 034, Telangana Tel: +91 40 39144444 Fax: +91 40 39144455 Email: somnath.marthi@iictechnologies.com Web: www.iictechnologies.com</p>
<p>M/s Zenith Surveys (I) Pvt. Ltd. Lakhani'sPlam View, First Floor, Office No. 889, Sector 48, Nerul, Navi Mumbai – 400 706 Tel/ Fax: +91-22- 27708011 Email: zenithsurveys703@gmail.com nyvmane@yahoo.com Web: www.zenithsurvey.com</p>	<p>M/s CNC Office No. S-12-92, Haware's Centurion Premises Coop. Soc. Ltd Plot no 88-91, Sector 19, NERUL, Navi Mumbai – 400706 Tel: +91 22 22660017/ +91 22 49747575 Cell No: +91 9920654848/ +91 7506097212 Email: sales@emariner.net</p>

SECTION – V**NAVAREA – VIII WARNINGS IN FORCE.**

1. All in force NAVAREA and NAVTEX messages are available for visualisation along with details of affected Charts and ENC's for mariners on **INDIAN WARNINGS INFORMATION AND NAVIGATION SERVICES (INDIA – WINS)** on www.hydrobharat.gov.in.
2. For details of NAVAREA limits and organisation/ coordination, please refer to Notice No. 12 of the Special edition of Indian Notice to Mariners – 2020.
3. NAVAREA VIII Warnings in force as on 01 Mar 23: -

2021 SERIES - 286 340 463 478 544 629 658 759 761 833
2022 SERIES - 049 093 117 118 134 162 180 194 237 253 259 270 286 313 391 423 436 437 445
 446 461 476 489 497 513 518 519 536 546 569 571 583 584 601 606 615 617 646 651 656 688
 691 702 757 805 824 856 931 956 970 980 997 1002 1011
2023 SERIES - 004 015 036 037 063 064 071 081 090 104 105 111 112 115 116 126 127 136 137
 143 144 145 147 148 150 151 161 162 167 168 170 171 172 173 174 175 177 178 179 180 181
 182 183 184 185 186 187 188 189 190 191 192 193 194 195

4. NAVAREA VIII Warnings issued during the period from 16 Feb 23 to 28 Feb 23 (both dates inclusive) are as tabulated below: –

147. India West Coast - off Okha. Charts IN 21 202 251 INT 7318. Coastal Triumph will carry out survey from 17 Feb to 10 Mar 23 in areas bounded by (a) 22-37.48N 068-35.52E, 22-37.49N 068-40.66E, 22-30.78N 068-40.68E, 22-30.77N 068-35.54E (b) 22-41.41N 068-53.21E, 22-41.41N 068-59.19E, 22-35.95N 068-59.19E, 22-35.94N 068-53.21E. Wide berth of 500m requested.

2. Cancel this MSG 101830 UTC Mar 23.

148. India West Coast - off Mumbai. Charts IN 21 254 255 292 INT 7334. Fugro Mapper progressing seabed survey in vicinity of 19-48.11N 072-22.69E, 19-46.01N 072-03.25E, 19-31.80N 071-17.40E, 18-34.96N 072-14.46E, 19-06.08N 070-56.43E, 18-39.23N 070-58.86E, 18-45.65N 072-19.22E, 18-18.64N 072-21.82E, 19-19.47N 071-12.07E, 19-20.06N 072-01.27E, 20-08.68N 071-44.94E, 19-10.88N 072-07.03E. Length of tow 150 meters from stern. Wide berth requested.

2. Cancel this MSG 151830 UTC Mar 23.

149. India West Coast - off Mumbai. Charts IN 21 211 255 292 INT 7021. Albatross 5, AL Marwa, Akash III progressing survey in areas bounded by (a) 19-05.45N 072-47.52E , 19-05.77N 072-46.97E, 19-04.65N 072-46.43E, 19-04.32N 072-46.98E (b) 19-01.90N 072-41.90E, 19-04.31N 072-47.03E, 19-04.79N 072-46.73E, 19-02.45N 072-41.61E (c) 18-59.51N 072-40.37E, 19-02.37N 072-41.64E, 19-02.11N 072-42.14E, 18-59.26N 072-40.93E (d) 18-58.77N 072-40.36E, 18-59.22N 072-39.97E, 18-59.68N 072-40.60E, 18-59.23N 072-40.99E (e) 18-59.31N 072-40.23E, 18-58.95N 072-39.04E, 18-58.46N 072-39.24E, 18-58.80N 072-40.42E (f) 18-57.37N 072-33.93E, 18-56.81N 072-34.11E, 18-58.46N 072-39.24E, 18-59.01N 072-39.03E. Wide berth from area advised.

2. Cancel this MSG 281830 UTC Feb 23.

150. India West Coast - Gulf of Khambhat. Charts IN 21 208 254 INT 7331. Wenna, Trewenna and Kohinoor-1 will carry out seismic survey in area bounded by 22-13.39N 072-22.48E, 22-13.40N 072-25.03E, 22-11.22N 072-25.14E, 22-11.27N 072-28.65E, 22-13.59N 072-28.74E, 22-13.68N 072-30.90E, 22-02.85N 072-31.15E, 22-02.85N 072-30.27E, 21-52.75N 072-30.36E, 21-52.69N 072-33.45E, 21-49.19N 072-33.46E, 21-48.98N 072-19.75E, 21-54.34N 072-19.72E, 21-54.35N 072-22.68E from 17 Feb to 14 Mar 23. Wide berth requested.

2. Cancel this MSG 141830 UTC Mar 23.

151. India West Coast - off Mumbai. Charts IN 21 255 292 INT 7334. Posh Natuna, Posh Arcturus and Posh Paglima will carry out pipeline replacement survey in vicinity of 18-34.93N 072-14.43E, 19-24.62N 071-13.08E, 19-25.23N 071-11.47E, 19-20.06N 072-01.27E, 19-18.28N 071-58.59E, 19-25.62N 071-16.16E, 19-25.23N 071-16.86E, 19-22.41N 071-21.46E from 17 Feb to 12 Mar 23. Wide berth requested.

2. Cancel this MSG 121830 UTC Mar 23.

152. India West Coast - off Mumbai. Charts IN 21 255 292 INT 7334. DSV Seamec III will carry out survey in vicinity of 19-10.63N 070-56.75E. Wide berth requested.

2. Cancel this MSG 251830 UTC Feb 23.

153. India West Coast - off Dabhol. Charts IN 21 256 293 INT 7340. Oceanic Sirius will carry out seismic survey in area bounded by 18-04.84N 072-32.84E, 17-10.07N 072-32.81E, 17-10.08N 072-17.18E, 18-04.83N 072-17.13E from 17


<p>153. Continued Feb to 25 Feb 23. Tow length 10km. Wide berth requested. 2. Cancel this MSG 251830 UTC Feb 23.</p>
<p>154. India East Coast - off Balasore. Charts IN 31 351 INT 756. Experimental flight trials scheduled from 20 to 22 Feb 23 from 0430 to 0630 UTC and 0900 to 1100 UTC in danger area bounded by 21-36.90N 087-30.07E, 21-02.72N 088-52.75E, 19-27.23N 087-32.52E, 20-09.60N 086-36.72E, 20-42.18N 087-08.98E, 20-57.35N 086-54.47E. Wide berth from area advised. 2. Cancel this MSG 221200 UTC Feb 23.</p>
<p>155. India West Coast - off Ponnani. Charts IN 22 259 INT 7356. Firing scheduled 18, 19 Feb 23 from 0430 to 1130 UTC in danger area bounded within 10-39N TO 10-49N and 075-20.50E to 075-30E. Wide berth from area advised. 2. Cancel this MSG 191230 UTC Feb 23.</p>
<p>156. Andaman Sea - off Car Nicobar I. Charts IN 33 407 472 INT 755. Responder will carry out cable installation works in areas bounded by (a) 09-37.13N 092-52.62E, 09-37.69N 092-43.62E, 09-33.94N 092-43.42E, 09-33.27N 092-52.50E from 20 to 22 Feb 23 (b) 09-40.00N 092-46.01E, 09-23.67N 091-07.69E, 09-29.11N 089-51.30E, 09-08.30N 088-20.42E, 09-00.70N 088-22.19E, 09-21.33N 089-51.50E, 09-14.13N 091-14.15E, 09-32.03N 092-45.03E from 22 to 27 Feb 23. Wide berth requested. 2. Cancel this MSG 271830 UTC Feb 23.</p>
<p>157. India West Coast - off Ponnani. Charts IN 22 220 259 294 INT 7356. Firing by CG aircraft scheduled from 21 to 23 Feb 23 from 0400 to 0630 UTC in danger area bounded by 10-50N 075-35E, 10-20N 075-40E, 10-20N 075-10E, 10-50N 075-00E. Wide berth from area advised. 2. Cancel this MSG 230730 UTC Feb 23.</p>
<p>158. India East Coast - Chennai. Charts IN 33 313 356 3001 INT 7400. Firing scheduled on 21 Feb 23 from 0830 to 0930 UTC in danger sector extending upto 11 Nm between bearing 045 and 075 from 13-07.02N 080-18.01E. Wide berth from area advised. 2. Cancel this MSG 211030 UTC Feb 23.</p>
<p>159. India West Coast - off Porbandar. Charts IN 21 252 292 INT 7021. Firing by CG aircraft scheduled on 22 Feb 23 from 0330 to 0930 UTC in danger area bounded by 21-32N 069-24E, 21-17N 069-24E, 21-17N 069-06E, 21-32N 068-56E. Wide berth from area advised. 2. Cancel this MSG 221030 UTC Feb 23.</p>
<p>160. Andaman Sea - off Barren I. Charts IN 41 473 INT 7031. Firing by CG aircraft scheduled 21, 24 Feb 23 from 0730 to 0930 UTC in danger area bounded within 11-50N to 12-00N and 093-40E to 094-10E. Wide berth from area advised. 2. Cancel this MSG 241030 UTC Feb 23.</p>
<p>161. India West Coast - off Nindakara. Charts IN 22 221 260 2032 INT 7362. Tug Savithri reported sunk in approximate position 08-57.43N 076-31.83E.</p>
<p>162. India West Coast - Gulf of Khambhat. Charts IN 21 207 254 292 INT 7021. Narmada channel buoy number 7 relaid in new position (20-56.00N 072-09.40E).</p>
<p>163. NAVAREA VIII - Warnings in force as on 17 Feb 2023 2021 Series - 147 286 340 463 478 479 544 629 658 759 761 833 2022 Series - 049 093 117 118 134 162 180 194 237 253 259 270 286 313 391 423 436 437 445 446 461 476 489 497 513 518 519 536 546 569 571 583 584 601 606 615 617 623 646 651 656 688 691 702 757 805 824 856 883 931 956 970 980 997 1002 1011 2023 Series - 004 015 034 036 037 040 042 060 063 064 067 069 071 079 081 083 088 090 092 096 099 100 102 104 105 111 112 115 116 119 124 126 127 128 134 135 136 137 143 144 145 146 147 148 149 150 151 152 153 154 155 156 157 158 159 160 161 162 (A) NAVAREA VIII warnings less than 42 days promulgated via safety net. (B) Text of NAVAREA VIII warning in force including those which no longer broadcast available in www.hydrobharat.gov.in 2. Cancel this MSG 241830 UTC Feb 23.</p>
<p>164. Cancel NAVAREA VIII MSG 088/23, 099/23, 119/23, 124/23 and this MSG. INTM 050(T) 04/23 refers.</p>
<p>165. India East Coast - Chennai. Charts IN 32 356 391 3001 INT 7402. DGPS (13-25.20N 080-19.78E) transmission will be switched off from 220030 UTC to 231230 UTC Feb 23 for maintenance. 2. Cancel this MSG 231230 UTC Feb 23.</p>
<p>166. India West Coast - off Mumbai. Charts IN 21 255 292 293 INT 7021. LTB 300, AHT Shakti and AHT Maria 1 will carry out pipeline installation in vicinity of 19-22.45N 071-21.46E, 19-25.05N 071-14.48E, 18-34.97N 072-14.45E, 18-08.50N 072-22.07E from 21 Feb to 23 Mar 23. Wide berth requested. 2. Cancel this MSG 231830 UTC Mar 23.</p>
<p>167. India West Coast - off Mumbai. Charts IN 21 292 293 INT 7021. Seamec Princess will carry out pipeline survey (a) At various locations in area bounded by 19-13N TO 19-40N and 071-10E TO 071-28E (b) In vicinity of 19-12.75N 072-06.69E, 19-03.49N 072-12.28E, 18-55.55N 072-02.50E, 19-20.06N 072-01.26E, 19-18.28N 071-58.59E, 18-29.37N 072-14.75E, 18-08.44N 072-22.09E, 18-34.94N 072-14.43E, 18-33.72N 072-17.64E, 18-34.92N 072-14.46E, 18-30.08N 072-15.94E, 18-38.27N 072-14.04E, 18-41.46N 072-20.88E, 18-42.53N 072-20.47E, 18-43.45N 072-20.31E from 21</p>

<p>167. Continued Feb to 31 Mar 23. Wide berth requested. 2. Cancel this MSG 311830 UTC Mar 23.</p>
<p>168. India East Coast. Charts IN 31 355 INT 7405. Rig Move. West Polaris (16-16.06N 082-23.17E). Wide berth requested.</p>
<p>169. India East Coast - off Sagar I. Charts IN 31 301 351 INT 7419. Firing by CG aircraft scheduled 23 and 24 Feb 23 from 0430 to 1030 UTC in danger area bounded within 20-37N to 20-52N and 088-30E to 089-00E. Wide berth from area advised. 2. Cancel this MSG 241130 UTC Feb 23.</p>
<p>170. India West Coast - off Mumbai. Charts IN 21 253 255 292 INT 7334. Acoms 11 will carry out pipeline survey in areas bounded by (a) 19-42.47N 070-45.39E, 19-41.76N 071-40.36E, 18-55.88N 071-39.67E, 18-55.91N 070-44.90E (b) 18-46.37N 072-09.43E, 18-43.14N 072-24.05E, 17-58.80N 072-23.18E, 17-59.05N 072-08.57E (c) 19-27.83N 071-45.34E, 19-27.53N 072-12.95E, 18-59.58N 072-20.18E, 19-00.14N 071-46.33E (d) 20-40.94N 071-43.28E, 20-40.48N 072-09.69E, 20-04.22N 072-08.95E, 20-04.65N 071-42.66E from 22 Feb to 21 Mar 23. Wide berth requested. 2. Cancel this MSG 211830 UTC Mar 23.</p>
<p>171. India West Coast - off Mumbai. Charts IN 21 211 255 292 INT 7334. GS Rashi progressing pipeline survey in areas bounded by (a) 18-51.21N 072-37.45E, 18-49.08N 072-39.32E, 18-49.05N 072-38.54E, 18-51.45N 072-36.31E (b) 18-55.60N 072-30.71E, 18-54.16N 072-33.70E, 18-53.47N 072-33.85E, 18-54.81N 072-30.94E (c) 18-41.03N 072-30.94E, 18-42.40N 072-34.14E, 18-41.24N 072-33.94E, 18-39.65N 072-30.67E (d) 20-26.95N 072-39.46E 20-26.30N 072-43.75E, 19-49.42N 072-22.93E, 19-53.47N 072-16.77E (e) 19-12.46N 072-06.18E, 19-12.39N 072-08.26E, 19-44.70N 072-20.12E, 19-45.22N 072-18.95E (f) ALONG 19-48.99N 072-20.97E, 19-48.62N 072-21.45E . Wide berth requested. 2. Cancel this MSG 141830 UTC Mar 23.</p>
<p>172. India West Coast - off Kochi. CHARTS IN 22 272 273 INT 752. Maram will carry out cable operations in area bounded by 10-07.74N 076-10.82E, 10-09.51N 076-10.28E, 12-25.53N 071-51.16E, 07-45.24N 072-41.87E from 24 Feb to 04 Jun 23. Wide berth from area advised. 2. Cancel this MSG 041830 UTC Jun 23.</p>
<p>173. India West Coast. Charts IN 21 292 255 INT 7334. Rig move. Vivekanand-2 (18-39.22N 070-58.86E) and Parameswara (19-31.78N 071-17.39E). Refer to 050(T) of INTM 04/23. Wide berth requested.</p>
<p>174. India West Coast - off Mangalore. Charts IN 22 294 7703 INT 703. SW BLY progressing seismic survey in area bounded by 14-36.12N 071-22.34E, 11-02.67N 072-39.8E, 10-04.83N 068-24.79E, 10-52.1N 068-07.34E, 11-39N 068-0.23E, 12-37N 068-08.17E, 13-39.59N 068-25.5E, 14-0.22N 068-40.68E from 23 Feb to 01 Mar 23. Wide berth requested. 2. Cancel this MSG 011830 UTC Mar 23.</p>
<p>175. India West Coast - off Mumbai. Charts IN 21 255 292 INT 7334. Sea Stallion, Sea Conquest, Sea Jaguar and Sea Melody progressing installation activities in area bounded by 19-42.47N 070-45.40E, 19-41.66N 071-47.37E, 18-55.08N 071-46.56E, 18-55.92N 071-44.90E. Wide berth requested. 2. Cancel this MSG 131830 UTC Mar 23.</p>
<p>176. India East Coast - off Chennai. Charts IN 32 313 356 391 INT 7400. Firing by CG aircraft scheduled on 27 Feb 23 from 0130 to 1130 UTC in danger area bounded within 12-49N to 12-59N And 080-46E to 081-26E Wide berth from area advised. 2. Cancel this MSG 271230 UTC Feb 23.</p>
<p>177. Lakshadweep Sea. Charts IN 22 7703 7706 INT 752. SW Cook will carry out seismic survey in area bounded by 09-54.33N 074-55.36E, 08-41.77N 076-09.87E, 08-01.36N 076-48.01E, 07-15.43N 075-07.26E, 07-48.04N 074-51.02E, 07-34.26N 073-23.52E, 07-52.13N 070-42.52E, 08-59.01N 070-23.72E from 26 Feb to 12 Mar 23. Wide berth Requested. 2. Cancel this MSG 121830 UTC Mar 23</p>
<p>178. Indian Ocean - off Mauritius. Charts IN CHARTS BA 711 712 INT 7737. Salvage operation of MV Wakashio being progressed in vicinity of 20-26.6S 057-44.6E and area bounded by 20-26.1S 057-43.1E, 20-25.1S 057-44E, 20-24S 057-45.5E. Wide berth of 2 Nm requested. 2. Cancel NAVAREA VIII MSG 147/21.</p>
<p>179. Arabian Sea - Agatti I. Charts IN 268 2047 INT 7353 . Racon B (10-52.51N 072-12.3E) not operating in S-Band and X-Band. 2. Cancel NAVAREA VIII MSG 479/21.</p>
<p>180. Indian Ocean. Charts IN 7071 7707 INT 707. R/V Hakuohmaru will carry out ADCP and M-Triton buoy deployment and retrieval in vicinity of 00-00.06N 090-14.96E, 04-57S 094-58.50E, 05-04.84S 095-07.10E, 08-13.05S 095-07.41E from 25 Feb to 04 Mar 23. Wide berth requested. 2 Cancel this MSG 041830 UTC Mar 23.</p>
<p>181. India East Coast - off Balasore. Charts IN 31 351 INT 756. Experimental flight trials scheduled from 27 Feb to 02 Mar 23 from 0430 to 0630 UTC and 0900 to 1100 UTC in danger area bounded by 21-14.92N 086-48.63E, 19-45.78N 087-48.07E, 21-02.72N 088-52.75E, 21-35.58N 087-10.70E. Wide berth from area advised. 2. Cancel this MSG 021200 UTC Mar 23.</p>
<p>182. NAVAREA VIII - Warnings in force as on 24 Feb 2023 2021 Series - 286 340 463 478 544 629 658 759 761 833</p>

<p>182. Continued 2022 Series - 049 093 117 118 134 162 180 194 237 253 259 270 286 313 391 423 436 437 445 446 461 476 489 497 513 518 519 536 546 569 571 583 584 601 606 615 617 646 651 656 688 691 702 757 805 824 856 931 956 970 980 997 1002 1011 2023 Series - 004 015 034 036 037 063 064 069 071 079 081 090 092 096 100 102 104 105 111 112 115 116 126 127 128 136 137 143 144 145 146 147 148 149 150 151 152 153 156 161 162 167 168 170 171 172 173 174 175 176 177 178 179 180 181 (A) NAVAREA VIII warnings less than 42 days promulgated via safetynet. (B) Text of NAVAREA VIII warning inforce including those which no longer broadcast available in www.hydrobharat.gov.in 2. Cancel this MSG 031830 UTC Mar 23.</p>
<p>183. Andaman Sea. Charts IN 33 41 7706 INT 706. Eagle explorer will carry out seismic survey in vicinity of 08-05.61N 090-24.17E, 06-01.30N 090-24.17E, 05-14.34N 090-48.86E, 04-20.63N 091-22E, 04-01.06N 091-49.71E, 04-01.06N 092-41.94E, 04-52.82N 093-23.77E, 05-48.11N 094-16.50E, 06-20.14N 094-35.19E, 06-20.14N 093-19.67E, 09-30.71N 093-19.67E, 09-30.71N 094-59.19E, 12-10.82N 094-59.19E, 12-10.82N 095-41.26E, 12-32.88N 095-41.26E, 12-32.88N 095-01.15E, 13-05.35N 095-01.15E, 13-05.35N 093-35.80E, 10-37.12N 093-35.80E, 10-37.12N 091-55.09E, 06-12.53N 091-55.09E, 06-12.53N 091-07.28E from 26 Feb to 06 Mar 23. Tow length 10km. Wide berth requested. 2. Cancel this MSG 061830 UTC Mar 23.</p>
<p>184. India West Coast - off Mormugao. Charts IN 22 293 294 7705 INT 705. Firing scheduled from 010430 UTC to 041130 UTC Mar 23 in danger area bounded by 17-42.60N 070-36.40E, 16-14.00N 067-43.00E, 13-50.00N 072-15.50E, 13-49.70N 073-06.60E, 15-37.90N 073-06.20E, 16-48.80N 072-30.00E, 17-38.00N 071-27.50E. Wide berth from area advised 2. Cancel this MSG 041230 UTC Mar 23.</p>
<p>185. India East Coast - off Gopalpur. Charts IN 31 305 352 353 391 INT 7413. Army air defence firing scheduled from 01 to 04 Mar, 10 to 31 Mar 23 from 0130 to 0830 UTC and 0930 TO 1430 UTC in danger area bounded by (a) 19-14.6N 084-53.7E (b) 19-07.39N 085-35.94E (c) 18-33.61N 084-53.74E and arc of 41 Nm radius joining point B and C. Wide berth from area advised. 2. Cancel this MSG 311530 UTC Mar 23.</p>
<p>186. India West Coast - off Porbandar. Charts IN 21 252 292 INT 7021. Firing by CG aircraft scheduled on 02 Mar 23 from 0330 to 0530 UTC in danger area bounded by 21-32N 069-24E, 21-17N 069-24E, 21-17N 069-06E, 21-32N 068-56E. Wide berth from area advised. 2. Cancel this MSG 020630 UTC Mar 23.</p>
<p>187. Bay of Bengal - off Myanmar. Charts IN 31 BA 817 INT 7430. Hyundai 2500, Lanpan 26 and Lanpan 34 will carry out survey in area bounded by 19-41.81N 092-30.80E, 19-41.82N 092-34.24E, 19-38.56N 092-34.25E, 19-38.55N 092-30.81E from 28 Feb to 30 Apr 23. Wide berth requested. 2. Cancel This MSG 301830 UTC Apr 23.</p>
<p>188. India West Coast - Vengurla Point. Charts IN 22 214 293 INT 7022. NAVTEX Transmitter (15-51.32N 073-37.89E) will be switched off from 280330 UTC Feb 23 for maintenance.</p>
<p>189. Bay of Bengal. Charts IN 33 7706 INT 755. Responder will carry out cable installation works in areas bounded by (a) 09-20.70N 088-26.07E, 09-14.93N 088-04.83E, 08-52.68N 088-12.15E, 08-58.74N 088-33.10E from 28 Feb to 02 Mar 23 (b) 09-14.14N 088-24.71E, 08-15.90N 086-05.80E, 08-02.17N 086-11.54E, 09-01.02N 088-28.72E from 02 to 05 Mar 23. Wide berth requested. 2. Cancel this MSG 051830 UTC Mar 23.</p>
<p>190. India West Coast - off Mumbai. Charts IN 21 255 292 INT 7021. Man overboard reported from BHS platform in approximate position 19-22.40N 071-21.40E at 241430 UTC Feb 23. Mariners to keep sharp lookout. 2. Cancel this MSG 031830 UTC Mar 23.</p>
<p>191. Lakshadweep Sea - off Kavaratti I. Charts IN 22 268 273 INT 7353. Firing scheduled on 03 Mar 23 from 0230 to 0630 UTC in danger area bounded within 10-15N to 10-30N and 072-40E to 072-55E wide berth from area advised. 2. Cancel this MSG 030730 UTC Mar 23.</p>
<p>192. India West Coast - off Mormugao. Charts IN 22 293 294 7705 INT 705. Firing Scheduled from 030200 UTC to 061700 UTC Mar 23 in danger areas bounded by (a) 17-42.60N 070-36.40E, 16-14.00N 067-43.00E, 13-50.00N 072-15.50E, 13-49.70N 073-06.60E, 15-37.90N 073-06.20E, 16-48.80N 072-30.00E, 17-38.00N 071-27.50E (b) 14-50N 073-53.50E, 14-35N 073-16E, 15-42N 072-47E, 15-57N 073-25E. Wide berth from area advised. 2. Cancel this MSG 061800 UTC Mar 23.</p>
<p>193. India West Coast - Kochi. Charts IN 22 220 259 2004 2029 INT 7356. Firing scheduled (a) 03, 10, 17, 24, 31 Mar 23 from 0900 to 1200 UTC and 1230 to 1430 UTC (b) 06, 13, 20, 27 Mar 23 from 0900 to 1200 UTC in danger area bounded by 09-57.5N 075-59.5E, 09-57.7N 076-14.2E, 09-44N 076-17.5E, 09-42.5N 076-09.5E. Wide berth from area advised. 2. Cancel this MSG 311530 UTC Mar 23.</p>
<p>194. Andaman Sea - off Barren I. Charts IN 41 473 INT 7031. Firing by CG aircraft scheduled on 03 Mar 23 from 0730 to 0930 UTC in danger area bounded within 11-50N to 12-00N and 093-40E to 094-10E. Wide berth from area advised. 2. Cancel this MSG 031030 UTC Mar 23.</p>

195. India West Coast - off Ponnani. Charts IN 22 220 259 294 INT 7356. Firing by CG aircraft scheduled from 02 to 04 Mar 23 from 0400 to 0630 UTC in danger area bounded by 10-50N 075-35E, 10-20N 075-40E, 10-20N 075-10E, 10-50N 075-00E. Wide berth from area advised.

2. Cancel this MSG 040730 UTC Mar 23.



SECTION – VI
CORRECTIONS TO SAILING DIRECTIONS (PILOTS)

NIL

SECTION – VII
CORRECTIONS TO LIST OF LIGHTS

No	Name & Location	Position (Lat-Long)	Characteri stics	Ht. (mts)	Range (miles)	Structure & Height (mts)	Remarks
D6484	Cape St Lucia. N of Cape	28 30-89 S 32 23-97 E	FI(2)W 10s	112	24	White metal tower, black bands, white dome 8	<i>fl 0-5, ec 1, fl 0-5, ec 8.</i> W210°- 030° (180°). TE 2022 *
F1688	-- Cyrene	01 15-30 N 103 45-54 E	FI R 2-5s	8	R 8 R 5	Red concrete framework tower	Dual intensity, alternates between 8M and 5M
---	---	..	AIS	MMSI No 005631116 *

SECTION – VIII
CORRECTION TO LIST OF RADIO SIGNALS

INP 31(1), 2019

(Last correction: Edition No. 23 dated 01 Dec 2022)

NIL

INP 31(2), 2019

(Last correction: Edition No. 24 dated 01 Dec 2022)

NIL

INP 31(5), 2017

(Last correction: Edition No. 24 dated 16 Dec 2021)

NIL

INP 31(6), 2018

(Last correction: Edition No. 02 dated 16 Jan 2023)

PAGES 05, BANGLADESH, HIRAN POINT.

Delete entry and replace by:

HIRAN POINT 21°46'N 89°30'E

Pilots

CONTACT DETAILS:

Call: Pilot Station
VHF Channel: Ch 16; 11 14
Telephone: +88(0)247 8846166
+88(0)157 5274102
Fax: +88(0)247 7753778
E-mail: vtms@mpa.gov.bd
portcontrol@mpa.gov.bd
Website: www.mpa.gov.bd

HOURS: H24

PROCEDURE:

- (1) **Pilotage is compulsory** for all vessels over 200 GT.
- (2) **Notice of ETA:** Vessels should advise ETA to Port Control (via agents) and Pilots on VHF Ch 11, 24h prior to arrival at Mongla Fairway Lt buoy (21°26'·90N 89°34'·40E). The ETA message should include the following information:
 - (a) ETA at Mongla Fairway Lt buoy
 - (b) Forward Draught
 - (c) Speed, LOA and GT
 - (d) Flag
 - (e) Fresh water requirements
 - (f) Type and amount of cargo
 - (g) Local agent
- (3) Vessels should arrive at Mongla Fairway Lt buoy at least 3h prior to HW at Hiran Point to enter on a particular day.
- (4) On or before arrival at the Mongla Fairway Lt buoy, vessels should contact the Pilot Station on VHF Ch 16 for bar crossing instructions.
- (5) **Pilot boards** in the following positions:
 - (a) 21°50'·00N 89°31'·48E (Fair weather)
 - (b) 21°58'·43N 89°31'·44E (Bad weather)

NOTE:

Provides pilotage for KHULNA and MONGLA.

Vessel Traffic Management and Information System

DESCRIPTION:

The VTMS system has been established to improve the safety, security and safe navigation of vessels entering the Pussur Channel of Mongla Port.

CONTACT DETAILS:**Hiran Point VTMS**

Call: Hiran Point VTMS
 VHF Channel: Ch 16; 11 14
 Telephone: +88(0)247 8846166
 +88(0)157 5274102
 Fax: +88(0)247 7753778
 E-mail: vtms@mpa.gov.bd
 portcontrol@mpa.gov.bd
 Website: www.mpa.gov.bd

Mongla VTMS

Call: Mongla VTMS
 VHF Channel: Ch 16; 11 14
 Telephone: +88(0)247 8846166
 +88(0)140 4411856
 Fax: +88(0)247 7753778
 E-mail: vtms@mpa.gov.bd
 portcontrol@mpa.gov.bd
 www.mpa.gov.bd

HOURS: H24

PROCEDURE:

- (1) Vessels are required to contact the VTMS as follows:
 - (a) On arrival at the fairway providing the following:
 - (i) LOA
 - (ii) Breadth
 - (iii) GT
 - (iv) NT
 - (v) Draught
 - (b) On anchoring providing the following:
 - (i) Time
 - (ii) Position
 - (c) When weighing anchor providing the time underway
 - (d) When passing the following lines of latitude:
 - (i) 21°27'.16N 89°32'.49E
 - (ii) 21°31'.52N 89°27'.79E
 - (iii) 21°38'.04N 89°27'.57E
 - (iv) 21°41'.68N 89°28'.43E
 - (v) 21°46'.49N 89°28'.64E
 - (vi) 21°49'.33N 89°30'.86E
- (2) Vessels at anchor are required to maintain a 24h listening watch on VHF Chs 11 and 16.
- (3) Vessels are required to contact Hiran Point VTMS via VHF when arriving within a radius of 30 nautical miles from the Fairway Lt Buoy (21°26'.86N 89°33'.97E).
- (4) Vessels should contact Hiran Point VTMS via VHF providing their ETA 3h prior to arrival.
- (5) Vessels will be advised by the VTMS an anchorage position (if required) and a Pilot boarding position.
- (6) Vessels are required to provide the following arrival information via e-mail:
 - (a) Vessel's name
 - (b) Call sign
 - (c) IMO No
 - (d) MMSI No
 - (e) Flag
 - (f) LOA
 - (g) GT
 - (h) DWT
 - (j) ETA
 - (k) Beam
 - (l) Last port of call
 - (m) Next port of call
 - (n) Cargo
 - (o) Arrival draught
 - (p) Departure draught
 - (q) Arrival DWT
 - (r) Freeboard
 - (s) Pilot boarding arrangements
 - (t) Name of local agent
 - (u) Departure DWT

8.3

- (u) Any defects to hull, machinery or equipment which could adversely affect safe operation or delay commencement of cargo handling

RADAR SURVEILLANCE:

- (1) Three Radar surveillance navigation systems are located as follows:
- (a) Hiran Point (21°48'·80N 89°27'·90E)
 - (b) Harbaria (22°17'·93N 89°95'·84E)
 - (c) Mongla (22°28'·40N 89°35'·65E)
- (2) These systems will allow vessels to enter the navigation channel safely on the fairway between Jafford Point Lt (21°45'·40N 89°32'·80E) and Hiran Point Lt (21°47'·83N 89°28'·37E) and the Pilot boarding ground.
- (3) The VTMISS guidance is provided by Hiran Point Pilot Station.

PAGES 06, BANGLADESH, KHULNA. BELOW Pilots and Port, Procedure Section

Insert:

Vessel Traffic Management and Information System

For details see HIRAN POINT.

PAGES 06, BANGLADESH, MONGLA. BELOW Pilots and Port Section, Note

Insert:

Vessel Traffic Management and Information System

For details see HIRAN POINT.

SECTION – IX

REPORTING OF NAVIGATIONAL DANGERS

Appeal to all Mariners

1. Mariners at sea whilst on passage, or whilst entering / leaving ports / Harbour and other waterways, are requested to look out for new or suspected dangers to navigation, changes in aids to navigation, or corrections to published charts and Sailing Directions. Whenever any such changes / dangers are observed, mariners are requested to notify the same to the Chief Hydrographer to the Government of India at the following address: -

National Hydrographic Office
107-A, Rajpur Road,
Dehradun - 248001
(Uttarakhand), India

e-mail : msis-inho@navy.gov.in, inho@navy.gov.in
Fax No. : +91-135- 2748373
Web : www.hydrobharat.gov.in

Instructions for filling up IH 102

2. Kindly follow the instructions below in order to help the Hydrographic Office (the recipient) to quickly issue NAVAREA warning / Notice to Mariners for the benefit of all other mariners at sea.

Position Reporting

3. Accurate position or knowledge of position error is of great importance. Latitude and Longitude should only be used to specify position details when they have been fixed by GPS or Astronomical Observations. A full description of the method, equipment, time and datum (WGS 84/Everest/Other) used should be given. When position is defined by sextant angles or bearings (true or magnetic to be specified), more than two bearings should be used in order to provide a redundancy check. Distances observed by Radar should be corrected for index errors. Where position is derived after the event, from other observations and/or Dead Reckoning, the methodology of deriving the position should be included.

4. Paper Charts. A copy/tracing of largest scale chart is the best medium for forwarding details, the alterations and additions being shown thereon in red, but adequate details from the chart must be traced in black ink to enable the amendments to be fitted correctly.

5. ENCs. A Screen shot of largest scale usage band ENC with the alterations and additions being shown thereon in red. If it is to report an issue with the display of an ENC, a screen shot of the affected cell should be sent along with details of the ECDIS make and version in use at the time.

Depth Reporting

6. When soundings are obtained using echo sounders, the echo sounding trace should be duly annotated with date, times, position, depths, etc., and forwarded with the IH102. It is important to state whether the echo sounder is set to register depths below the surface or below the keel; in the latter case the vessel's draught should be given. Time and date should be given in order that corrections for the height of the tide may be made where necessary. The make, name and type of echo sounder should also be given.

7. For modern echo sounders that use electronic 'range gating', care should be taken that the correct range scale and appropriate gate width are in use. Older electro-mechanical echo sounders frequently record signals from echoes received back after one or more rotations of the stylus have been completed. Thus with a set whose maximum range is 500m, an echo recorded at 50m may be from depths of 50m, 550m or even 1050m. Soundings recorded beyond the set's nominal range can usually be recognised by the following:

- (a) The trace being weaker than normal for the depth recorded;
- (b) The trace passing through the transmission line;
- (c) The feathery nature of the trace.


As a check that apparently shoal soundings are not due to echoes received beyond the set's nominal range, soundings should be continued until reasonable agreement with charted soundings is reached. However, soundings received after one or more rotations of the stylus can still be useful and should be submitted if they show significant differences from the charted depths. Efforts should be made to identify and negate false echoes if any. The Mariners Handbook (NP100) and Notice 15 Special Edition of Notice to Mariners may be consulted.


8. Reports which cannot be confirmed or are lacking in certain details should not be withheld. Shortcomings should be stressed and any firm expectation of being able to check the information on a succeeding voyage should be notified.

9. Reports of **shoal soundings**, uncharted dangers and aids to navigation out of order should, at the mariner's discretion, also be made by radio to the nearest coast radio station. The draught of modern tankers in such that any uncharted depth under 30 meters or 15 fathoms may be of sufficient importance to justify a radio message.

10. Changes to Port information should be forwarded on Form IH.102A together with form IH.102. Form 102A contains the information required for Sailing Directions and should be used as an *aide memoir*. The Mariners Handbook, NP100, Chapter 8 gives general instructions. Where there is insufficient space on the forms an additional sheet should be used.

Please Note: - An acknowledgement will be sent by National Hydrographic Office for Hydrographic Notes, on receipt. When a Notice to Mariners is issued, the sender's ship or name is quoted as authority unless the information is also received from other authorities/ foreign Notices to Mariners. Further, communication from National Hydrographic Office to the sender of Hydrographic Notes will only be necessary to verify unusual features or abnormal values reported.



HYDROGRAPHIC NOTE				IH.102 (Revised 2012)	
For Forwarding information for Indian Charts, ENCs and Publications and reporting of ENC related issues					
Date			Ref. Number		
Name of the Ship or Sender					
Address					
Tel/FAX/E-mail address					
Observation Date			Time (UTC/IST)		
Object of Changes Observed (Tick appropriate)	<input type="checkbox"/> Bathymetry		<input type="checkbox"/> Nav. Dangers		<input type="checkbox"/> Nav. aids
	<input type="checkbox"/> Designated Areas		<input type="checkbox"/> Others		
Geographical Position (See Instructions Overleaf)	Latitude		Longitude		
Position Method	<input type="checkbox"/> DGPS	<input type="checkbox"/> GPS	<input type="checkbox"/> Radar	<input type="checkbox"/> Others	
Datum Used	<input type="checkbox"/> WGS84	<input type="checkbox"/> Everest		<input type="checkbox"/> Others	
Charts Affected				Edition	
Latest Edition of Indian Notices to Mariners Held					
Tracing/Plot/Photograph if enclosed					
ENCs Affected					
Latest Update Disk Held					
Publication Affected				Edition	
Page No./Light No. etc					
Details:					
					
Limitations if any in Reporting the Changes Above					
Details of Documents/Photos attached:					
Signature of the Master/Reporter/Observer					

HYDROGRAPHIC NOTE FOR PORT INFORMATION (To accompany Form IH.102)		IH.102A (Revised 2012)	
Date		Ref. No.	
Name of the Ship or Sender			
Address			
Tel/Fax/E-mail			
1. NAME OF PORT			
Location	Latitude		Longitude
2. GENERAL REMARKS			
Principal activities and trade			
Number of ships and tonnage handled per year			
Maximum size of draught of vessel handled			
Copy of Port handbook (if available)			
3. ANCHORAGES			
Type / Purpose			
Minimum depth at anchorage			
Shelter afforded			
Holding ground			
Recommended pilotage to the anchorage			
4. PILOTAGE			
Authority for request			
Embarkation position			
Regulations			
Documents to be provided			
Recommended pilotage to approach of Harbour and Berths			
Information on VTMS			
5. DIRECTIONS			
Entry and Berthing Information			
Tides (Height)			
Tidal Stream Information			
Wind Speed and Direction			
Navigational Aids (Beacons / Buoys / Lights / Etc.)			
6. POLLUTION CONTROL			
Local regulation in force (If Any)			
7. TUGS			
Number available / Tug type			
Maximum HP / Bollard pull			

7. TUGS (Continued)	
Requesting authority	
Availability timing / Communication	
Hiring charges	
8. BERTHING AND WHARVES	
Type & Number of berths available	
Length	
Depth alongside	
Facilities available	
Procedure for requesting berth & hiring charges	
9. CARGO HANDLING	
Containers	
Lighters & Ro-Ro etc.	
10. CRANES	
Brief details of Max. lifting capacity, Height of boom at wharf level and Outreach	
Container handling facilities	
11. BRIDGES	
Vertical clearance	
12. REPAIRS	
Hull machinery and underwater	
Ship and Boat yards	
Docking or Slipway facilities (Size/ Dimensions of vessels handled)	
Hards and Ramps	
Divers / Diving assistance	
13. SERVICES	
Radio / FAX / Telephone / Internet etc.	
Medical	
Quarantine	
Consul	
Ship chandlery and Stevedores	
Compass adjustment	
Tank cleaning	
Hull painting	
Police / Ambulance / Firefighting (Fixed and Mobile facilities)	
Nav. Warning and Weather bulletin	
Garbage disposal / Waste oil disposal	
Helicopter landing facilities	

14. RESCUE & DISTRESS	
Salvage, Lifeboat, Life guards, etc	
15. SUPPLIES	
Fuel (Type, Quantities & Method of delivery)	
Fresh water (Method of delivery and Rate of supply)	
Provisions	
Chart agents	
16. COMMUNICATIONS	
Road, Rail and Air services available	
Nearest airport or airfield	
Port Radio and Information Service (Frequencies and Operating Hours)	
17. PORT AUTHORITY	
Designation, Address, Telephone, E-mail Address and Website	
18. SECURITY	
Security of ports / International Ship and Port Facility Security (ISPS) compliance	
Custom and Immigration Regulations in force	
19. SMALL CRAFT FACILITIES	
Information and facilities for small craft, yachts visiting the port	
Yacht clubs, berths etc	
20. SHORT LEAVE	
21. CLUBS RECREATION	
Information Kiosk (Location)	
Foreign Exchange firms / Banks (Within / Near Port Area)	
Places of interest near port	
22. VIEWS	
Photographs(Duly annotated) of the approaches, leading marks, the entrance to the harbour etc.	
23. ADDITIONAL DETAILS	
Any other information considered to be useful for the mariners	
SIGNATURE OF THE OBSERVER / REPORTER / MASTER	



FOR 24 X 7 SAR ASSISTANCE IN INDIAN SRR

Email: mrcc-west@indiancoastguard.nic.in

NATION WIDE SAR TELE: 1554 (LAND LINE)

INMARSAT C (IOR) 441907210 CODE: 43 (TOLL FREE)

AFTN: VABBYXYC