

***034 (T) (01/22) INDIA – WEST COAST – Vizhinjam Anchorage, Alleppey Anchorage – Buoys.**

Source: Adani Vizhinjam Port Pvt. Ltd.

1. Intensive shoreline monitoring of the coast 20 KM on either side of Vizhinjam Port is in progress. As part of the project 03 Turbidity buoys and 01 Wave Rider Buoy along with 05 navigational buoys is placed in following position:-

| Buoy | Location | Navigational Buoy | Location |
|----------------------|----------------------------|--------------------------|----------------------------|
| Wave Rider Buoy | 08° 20'·98N., 77° 08'·13E. | C2 | 08° 22'·21N., 76° 59'·28E. |
| Turbidity Buoy No. 1 | 08° 21'·83N., 76° 59'·24E. | C3 | 08° 21'·85N., 76° 59'·08E. |
| Turbidity Buoy No. 2 | 08° 22'·33N., 76° 59'·20E. | C4 | 08° 21'·38N., 76° 59'·74E. |
| Turbidity Buoy No. 3 | 08° 21'·70N., 76° 59'·56E. | C5 | 08° 20'·80N., 77° 00'·28E. |
| | | C6 | 08° 20'·94N., 77° 00'·43E. |

2. The buoys have been deployed for a probable duration of 03 years.

3. Vessels are advised to navigate with caution and contact local port authorities for more information.

Charts Affected – 260 (INT 7362) – 261 – 222 – 223 – 2012

Former INM 037(T)/20 is cancelled.