



*139 (T) (13/22)	INDIA – EAST COAST – PARADIP TO PUSSUR RIVER –Buoy.	
Source: BNHOC Notice No. 25(T)/2022.		
1. Following buoys are missing:-		
Buoy	Position	
 <i>Fl(2)R.12s</i> <i>B-12</i>	21° 38'·42N., 89° 26'·96E.	
 <i>Fl.R.8s</i> <i>B-14</i>	21° 40'·05N., 89° 27'·56E.	
2. Mariners are advised to navigate with caution in the area.		
Charts Affected – 351 (INT 7419)		