

**\*060 (T) (05/23) BAY OF BENGAL AND ANDAMAN SEA – Andaman Sea – Installation Activities.**

Source: Myanmar Notice 03/2023.

1. Undersea Telecommunication Cable laying is being carried out in following areas till 15 April 2023.

(a) The repair of the defective cable is being carried out by the <b>ROV (Remotely Operated Underwater Vehicle)</b> along the following coordinates.	
SI No.	Position
01.	15° 25'·98N., 96° 31'·96E.
02.	15° 12'·82N., 96° 29'·08E.
(b) The new cable laying and connecting is being carried out by the ROV along the following coordinates.	
SI No.	Position
01.	14° 46'·42N., 96° 23'·52E.
02.	14° 44'·85N., 96° 23'·43E.
(c) New cable laying cross PTTEP gas pipeline is being carried out by the ROV along the following coordinates.	
SI No.	Position
01.	14° 12'·38N., 96° 21'·34E.
02.	14° 11'·84N., 96° 21'·34E.
(d) The installation of the main sub-line unit (1) is being carried out by the ROV along the following coordinates.	
SI No.	Position
01.	14° 07'·38N., 96° 22'·42E.
02.	14° 06'·63N., 96° 22'·11E.
(e) The installation of the main branch unit (1) is being carried out by the ROV along the following coordinates.	
SI No.	Position
01.	14° 07'·67N., 96° 23'·06E.
02.	14° 07'·16N., 96° 22'·41E.
2. Mariners are advised not to navigate, anchor or trawl within 500 km along the submarine cable laying and repairing coordinates and consult the local port authorities for the latest information.	
<b>Charts affected – 41 (INT 757)</b>	

