

*118 (T) (12/23)	INDIA – WEST COAST – Port Dabhol – Buoys.		
Source: KLL Terminal, Port Dabhol.			
1. Following channel buoys from KLL navigational channel are removed temporarily till 31 st Aug 2023:–			
Buoy Number	Characteristics	Positions	
Fairway	Fl(2)10s	17° 34′.34N	073° 04′.58E
1	Q.G	17° 33′.49N	073° 05′.65E
2	Q.R	17° 33′.64N	073° 05′.74E
3	Fl.G.10s	17° 32′.96N	073° 06′.44E
4	Fl.R.10s	17° 33′.13N	073° 06′.49E
6	Fl(2)R.15s	17° 32′.54N	073° 07′.30E
7	Fl(3)G.10s	17° 32′.02N	073° 07′.71E
8	Fl(3)R.10s	17° 32′.11N	073° 07′.90E
9	VQ	17° 31′.03N	073° 08′.68E
10	Q(9)	17° 31′.13N	073° 08′.84E
GL 11	Fl.G.10s	17° 31′.42N	073° 08′.22E
GL 12	FL.(2)G.15s	17° 31′.23N	073° 08′.41E
2. Mariners are advised to navigate with caution in the area and contact Port authority for latest information.			
Charts Affected – 212 – 256 (INT 7340) – 293 (INT 7022) – 2065.			