

*134 (T) (14/23)	INDIA – WEST COAST – Dighi Harbour (Murud – Janjira) and Approaches – Fairway Buoy.
Source: IH – 102, INS Sarvekshak.	
1.	Fairway Buoy at position 18° 17'·40N., 072° 49'·24E reported missing from present location.
2.	Mariners are advised to navigate with caution in the area and contact Port authority for latest information.
Charts affected – 211 – 212 – 254 (INT 7340) – 255 (INT 7334) – 2036 (INT 7352).	
<i>Former INTM 217 (T)/22 is cancelled.</i>	

