

*135 (T) (14/23)	INDIA – WEST COAST – Karwar Port – Buoy.
Source: Karwar Port.	
1.	Channel Marking buoy at position 14° 48′·76N., 074° 05′·67E reported missing from present location.
2.	Mariners are advised to navigate with caution in the area and contact Port authority for latest information.
Charts affected – 2008 – 2120 – 2353.	

