

<b>*091 (P) (13/24)</b>	<b>INDIA – WEST COAST – Vizhinjam Harbour – Construction Activity.</b>
Source: IH – 102, INS Sutlej.	
1. Construction of breakwater in Vizhinjam International Seaport Ltd (VISL) is in progress in the area bounded by the following coordinates:-	
Sl. No.	Position
1	08°22'.30N.,076°59'.68E
2	08°22'.31N.,076°59'.67E
3	08°22'.32N.,076°59'.65E
4	08°22'.36N.,076°59'.63E
5	08°22'.35N.,076°59'.62E
6	08°22'.32N.,076°59'.58E
7	08°22'.28N.,076°59'.55E
8	08°22'.24N.,076°59'.51E
9	08°22'.20N.,076°59'.47E
10	08°22'.16N.,076°59'.44E
11	08°22'.13N.,076°59'.41E
12	08°22'.10N.,076°59'.38E
13	08°22'.08N.,076°59'.37E
14	08°22'.07N.,076°59'.36E
15	08°22'.05N.,076°59'.35E
16	08°22'.02N.,076°59'.34E
17	08°21'.99N.,076°59'.34E
18	08°21'.97N.,076°59'.34E
19	08°21'.94N.,076°59'.34E
20	08°21'.90N.,076°59'.35E
21	08°21'.86N.,076°59'.37E
22	08°21'.82N.,076°59'.39E
23	08°21'.79N.,076°59'.43E
24	08°21'.76N.,076°59'.47E
25	08°21'.73N.,076°59'.53E
26	08°21'.69N.,076°59'.58E
27	08°21'.65N.,076°59'.64E
28	08°21'.57N.,076°59'.74E
29	08°21'.52N.,076°59'.81E
30	08°21'.49N.,076°59'.85E
31	08°21'.43N.,076°59'.90E
32	08°21'.39N.,076°59'.93E
33	08°21'.39N.,076°59'.92E
34	08°21'.42N.,076°59'.89E
35	08°21'.43N.,076°59'.89E
36	08°21'.45N.,076°59'.87E
37	08°21'.49N.,076°59'.83E
38	08°21'.53N.,076°59'.77E
39	08°21'.56N.,076°59'.74E
40	08°21'.59N.,076°59'.69E
41	08°21'.63N.,076°59'.65E

<b>*091 (P) (13/24)</b>	<b>INDIA – WEST COAST – Vizhinjam Harbour – Construction Activity. (Continued).</b>
42	08°21'.68N.,076°59'.59E
43	08°21'.70N.,076°59'.55E
44	08°21'.72N.,076°59'.51E
45	08°21'.75N.,076°59'.47E
46	08°21'.78N.,076°59'.42E
47	08°21'.79N.,076°59'.40E
48	08°21'.83N.,076°59'.37E
49	08°21'.86N.,076°59'.35E
50	08°21'.89N.,076°59'.34E
51	08°21'.93N.,076°59'.33E
52	08°21'.96N.,076°59'.32E
53	08°21'.99N.,076°59'.33E
54	08°22'.02N.,076°59'.33E
55	08°22'.06N.,076°59'.35E
56	08°22'.10N.,076°59'.37E
57	08°22'.12N.,076°59'.39E
58	08°22'.12N.,076°59'.40E
59	08°22'.15N.,076°59'.42E
60	08°22'.16N.,076°59'.42E
61	08°22'.19N.,076°59'.45E
62	08°22'.22N.,076°59'.48E
63	08°22'.25N.,076°59'.51E
64	08°22'.28N.,076°59'.54E
65	08°22'.29N.,076°59'.54E
66	08°22'.32N.,076°59'.56E
67	08°22'.33N.,076°59'.57E
68	08°22'.35N.,076°59'.58E
69	08°22'.36N.,076°59'.58E
2. Mariners are advised to navigate with caution in the area and contact Port authority for latest information.	
<b>Charts affected – 22 (INT 752) – 32 (INT 754) – 260 (INT 7362) – 261 – 222 – 223 – 2012 – 2111.</b>	