

092 (T) (13/24)*INDIA – WEST COAST – ESSAR Bulk Terminal– Buoys.**

Source: Reliance Industries Limited.

1. Following Navigational buoys are withdrawn temporarily for repair and maintenance:-

SI No.	Nomenclature	Position
01.	Red Buoy No 1	21° 02'·72N., 072° 39'·84E.
02.	Red Buoy No 2	21° 03'·49N., 072° 40'·30E.
03.	Green Buoy No 3	21° 04'·10N., 072° 41'·43E.
04.	Red Buoy No 4	21° 04'·61N., 072° 40'·94E.

Charts affected – 2044 – 2101 (INT 7347) – 2108.